



"Quick" Decommission & "Quick" Recommission Package

"Quick" Decommission

Mazak responsibilities: -		Mazak responsibilities: -	
	De-QUICK (Lathe machine)	De-QUICK (Machining Centre)	
0	Check absolute level	o Check absolute level	
0	Check turret test bar and mill	o Check squares	
	spindle alignment	o Check spindle(s) for noise	
0	Check spindle(s) for noise	o Fix all axis clamps	
0	Fix all axis clamps	o Back up machine data	
0	Back up machine data	o Disconnect from transformer	
0	Disconnect from transformer		
	Customer responsibilities: -	Customer responsibilities: -	
0	Customer responsibilities: - To supply all axis clamps	Customer responsibilities: - o To supply all axis clamps	
0		•	
	To supply all axis clamps	o To supply all axis clamps	
	To supply all axis clamps To remove tooling, fixtures, swarf and	To supply all axis clamps To remove tooling, fixtures, swarf and	
0	To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission	 To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission 	
0	To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission To disconnect ancillary equipment	 To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission To disconnect ancillary equipment 	
0	To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission To disconnect ancillary equipment To disconnect power and air supplies from	 To supply all axis clamps To remove tooling, fixtures, swarf and coolant prior to decommission To disconnect ancillary equipment To disconnect power and air supplies from 	

"Quick" Recommission

Mazak responsibilities: -			Mazak responsibilities: -		
	Re-QUICK (Lathe machine)		Re-QUICK (Machining Centre)		
0	*Remove axis clamps	0	Remove axis clamps		
0	*Check absolute level	0	Check absolute level		
0	*Check turret test bar and mill spindle	0	Check squares		
	alignment	0	Check spindle alignment		
0	Check spindles for noise	0	Check spindles for noise		
0	*Check all axes for noise	0	Check all axes for noise		
0	*Back up machine data	0	Back up machine data		
0	*Supply & install RD password	0	Supply & install RD password		
Customer responsibilities: -			Customer responsibilities: -		
0	To reconnect power and air supplies prior to	0	To reconnect power and air supplies prior to		
	recommission		recommission		
0	To refit and refill coolant tanks	0	To refit and refill coolant tanks		
0	To ensure clear and accessible working	0	To ensure clear and accessible working areas		
	areas	0	To arrange local suppliers to reconnect		
0	To arrange local suppliers to reconnect		ancillary equipment		
	ancillary equipment				